

**Flood Control Project Maintenance
Levee Inspections**

Maintenance Issue Types Only, Levee Inspection Report By Mile - Spring 2016

Reclamation District No. 0150 Merrit Island

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 Sutter Slough	Left	0.52	03/15/2016 03/15/2016	Pavel Kazi

LM Start	0.00	Rating **	A	Issue No.	4
LM End	0.00	Issue Type +	Ma	Location *	N/A
Category	Earthen Levee		GPS Latitude/Longitude		
			Start	End	
Item	Operations & Maintenance Manuals			°	°
				°	°
DWR ID	DWR_RD0150_01_s_2013_4				
Comment Code					
Inspector Comment					
This LMA has the updated O&M manuals for their district.					

No Photos

LM Start	0.00	Rating **	A	Issue No.	5
LM End	0.00	Issue Type +	Ma	Location *	N/A
Category	Earthen Levee		GPS Latitude/Longitude		
			Start	End	
Item	Emergency Supplies & Equipment			°	°
				°	°
DWR ID	DWR_RD0150_01_s_2013_5				
Comment Code					
Inspector Comment					
This LMA has adequate amount of flood fighting materials in a centralized location.					

No Photos

LM Start	0.00	Rating **	A	Issue No.	6
LM End	0.00	Issue Type +	Ma	Location *	N/A
Category	Earthen Levee		GPS Latitude/Longitude		
			Start	End	
Item	Flood Preparedness & Training			°	°
				°	°
DWR ID	DWR_RD0150_01_s_2013_6				
Comment Code					
Inspector Comment					
The crew of this LMA had flood fighting training from DWR.					

No Photos

* Location LS : Land Side N/A : Not Applicable WS : Water Side CR : Crown	** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable	N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	--	---	---

**Flood Control Project Maintenance
Levee Inspections**

Maintenance Issue Types Only, Levee Inspection Report By Mile - Spring 2016

Reclamation District No. 0150 Merrit Island

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 Sutter Slough	Left	0.52	03/15/2016 03/15/2016	Pavel Kazi

LM Start	0.03	Rating **	M	Issue No.	7
LM End	0.50	Issue Type +	Ma	Location *	LS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Vegetation			38.332483 °	38.328172 °
				-121.583042 °	-121.576431 °
DWR ID	DWR_RD0150_01_s_2016_7				
Comment Code					
V1 : Control annual grass and weeds on the levee slopes and easements.					
Inspector Comment					

Photo 1 of 1 : SP_2016_RD0150_15_7_20160318_00005.jpg



View of the vegetation on the landside slope of the levee.

LM Start	0.03	Rating **	M	Issue No.	1
LM End	0.50	Issue Type +	Ma	Location *	WS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Vegetation			38.332483 °	38.328171 °
				-121.583041 °	-121.576432 °
DWR ID	DWR_RD0150_01_s_2016_1				
Comment Code					
V1 : Control annual grass and weeds on the levee slopes and easements.					
Inspector Comment					

Photo 1 of 1 : SP_2016_RD0150_15_1_20160318_00004.jpg



View of the vegetation on the waterside slope of the levee.

LM Start	0.19	Rating **	A/W	Issue No.	3
LM End	0.19	Issue Type +	Ma	Location *	LS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Vegetation			38.331402 °	38.331402 °
				-121.580358 °	-121.580358 °
DWR ID	DWR_RD0150_01_s_2012_3				
Comment Code					
V4 : Elderberries are blocking visibility and flood fight capability.					
Inspector Comment					
Elderberry is trimmed and levee slope is accessible.					

Photo 1 of 1 : SP_2016_RD0150_15_3_20160318_00006.jpg



View of the elderberry on the landside toe of the levee. The elderberry doesn't block visibility and it is trimmed up 5 feet above the slope.

* Location LS : Land Side N/A : Not Applicable WS : Water Side CR : Crown		** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain		+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement	
--	--	---	--	---	--

**Flood Control Project Maintenance
Levee Inspections**

Maintenance Issue Types Only, Levee Inspection Report By Mile - Spring 2016

Reclamation District No. 0150 Merrit Island

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 Sutter Slough	Left	0.52	03/15/2016 03/15/2016	Pavel Kazi

LM Start	0.44	Rating **	M	Issue No.	2
LM End	0.49	Issue Type +	Ma	Location *	WS
Category	Supplemental			GPS Latitude/Longitude	
				Start	End
Item	2015 USACE Erosion Survey, DRAFT			38.328555 °	38.328020 °
				-121.577544 °	-121.576693 °
DWR ID	DWR_RD0150_01_s_2016_2				
Comment Code					
Inspector Comment					
2013 - Old toe repair unraveling. Bridge at upstream end of site. 2015: No observed changes. [2015 Site ID: STR_28-4_R]					

Photo 1 of 2 : SP_2016_RD0150_15_2_20160219_00001.jpg



USACE 2013 Photo #1

Photo 2 of 2 : SP_2016_RD0150_15_2_20160219_00002.jpg



USACE 2013 Photo #2

* Location LS : Land Side N/A : Not Applicable WS : Water Side CR : Crown		** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain		+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	--	---	--	---

**Flood Control Project Maintenance
Levee Inspections**

Maintenance Issue Types Only, Levee Inspection Report By Mile - Spring 2016

Reclamation District No. 0150 Merrit Island

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 02 Sacramento River	Right	7.81	03/15/2016 03/15/2016	Pavel Kazi

LM Start	0.39	Rating **	M	Issue No.	6
LM End	0.39	Issue Type +	Ma	Location *	WS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Slope Stability			38.332717 °	38.332717 °
				-121.572083 °	-121.572083 °
DWR ID	DWR_RD0150_02_s_2012_6				
Comment Code					
S2 : Repair the levee slope damaged by foot traffic and prevent access where possible.					
Inspector Comment					

LM Start	0.39	Rating **	M	Issue No.	6 (cont)
LM End	0.39	Issue Type +	Ma	Location *	WS

Photo 1 of 2 : SP_2016_RD0150_16_6_20160219_00002.jpg



Updated photo of the slope instability on the waterside of the levee looking upstream during spring 2014 inspection.

Photo 2 of 2 : SP_2016_RD0150_16_6_20160219_00003.jpg



Slope instability was found on the waterside of the levee looking upstream.

* Location LS : Land Side N/A : Not Applicable WS : Water Side CR : Crown		** Rating A : Acceptable N : Not Inspected/Rated M : Minimally Acceptable C : Corrected U : Unacceptable A/W : Acceptable but Monitor & Maintain		+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	--	---	--	---

**Flood Control Project Maintenance
Levee Inspections**

Maintenance Issue Types Only, Levee Inspection Report By Mile - Spring 2016

Reclamation District No. 0150 Merrit Island

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 02 Sacramento River	Right	7.81	03/15/2016 03/15/2016	Pavel Kazi

LM Start	0.56	Rating **	N	Issue No.	57
LM End	0.56	Issue Type +	Ma	Location *	WS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Trim / Thin Trees			38.334525 °	38.334525 °
				-121.570025 °	-121.570025 °
DWR ID	DWR_RD0150_02_s_2016_57				
Comment Code					
T5 : Tree stumps.					
Inspector Comment					

Photo 1 of 1 : SP_2016_RD0150_16_57_20160318_00114.jpg



View of tree stumps on the waterside shoulder of the levee looking downstream.

LM Start	0.71	Rating **	M	Issue No.	10
LM End	0.71	Issue Type +	Ma	Location *	WS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Encroachments			38.336228 °	38.336228 °
				-121.568332 °	-121.568332 °
DWR ID	DWR_RD0150_02_s_2013_10				
Comment Code					
DE : Debris					
Inspector Comment					

Photo 1 of 1 : SP_2016_RD0150_16_10_20160219_00006.jpg



Debris was found on the waterside slope of the levee looking downstream during Spring 2013 inspection.

* Location LS : Land Side N/A : Not Applicable WS : Water Side CR : Crown		** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable		N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain		+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement	
--	--	--	--	---	--	---	--

**Flood Control Project Maintenance
Levee Inspections**

Maintenance Issue Types Only, Levee Inspection Report By Mile - Spring 2016

Reclamation District No. 0150 Merrit Island

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 02 Sacramento River	Right	7.81	03/15/2016 03/15/2016	Pavel Kazi

LM Start	0.71	Rating **	M	Issue No.	59
LM End	0.71	Issue Type +	Ma	Location *	LS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Encroachments			38.336291 °	38.336291 °
				-121.568260 °	-121.568260 °
DWR ID	DWR_RD0150_02_s_2016_59				
Comment Code					
TR : Tree or limb					
Inspector Comment					
Damaged tree roots and trunks appear to damage landside slope of the levee.					

Photo 1 of 1 : SP_2016_RD0150_16_59_20160318_00115.jpg



View of tree trunks and roots on the landside of the levee looking upstream.

LM Start	1.14	Rating **	N	Issue No.	8
LM End	1.14	Issue Type +	Ma	Location *	LS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Trim / Thin Trees			38.340864 °	38.340864 °
				-121.562915 °	-121.562915 °
DWR ID	DWR_RD0150_02_s_2012_8				
Comment Code					
T5 : Tree stumps.					
Inspector Comment					

Photo 1 of 1 : SP_2016_RD0150_16_8_20160219_00004.jpg



View of a tree stump on the landward slope.

LM Start	1.56	Rating **	M	Issue No.	53
LM End	1.56	Issue Type +	Ma	Location *	WS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Encroachments			38.344881 °	38.344881 °
				-121.557524 °	-121.557524 °
DWR ID	DWR_RD0150_02_f_2015_53				
Comment Code					
PI : Pipe					
Inspector Comment					
Abandoned pipes were found on the waterside slope.					

Photo 1 of 1 : SP_2016_RD0150_16_53_20160219_00028.jpg



Abandon pipes and debris was found on the waterside of the levee.

* Location
LS : Land Side N/A : Not Applicable
WS : Water Side
CR : Crown

** Rating
A : Acceptable N : Not Inspected/Rated
M : Minimally Acceptable C : Corrected
U : Unacceptable A/W : Acceptable but Monitor & Maintain

+ Issue Type
Ma : Maintenance Deficiency
Ob : Design & System Obsolescence
En : Enforcement

**Flood Control Project Maintenance
Levee Inspections**

Maintenance Issue Types Only, Levee Inspection Report By Mile - Spring 2016

Reclamation District No. 0150 Merrit Island

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 02 Sacramento River	Right	7.81	03/15/2016 03/15/2016	Pavel Kazi

LM Start	1.89	Rating **	M	Issue No.	50
LM End	1.89	Issue Type +	Ma	Location *	WS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Encroachments			38.346323 °	38.346323 °
				-121.551568 °	-121.551568 °
DWR ID	DWR_RD0150_02_f_2014_50				
Comment Code					
PI : Pipe					
Inspector Comment					
An abandoned pipe was found on the waterside of the levee.					

Photo 1 of 1 : SP_2016_RD0150_16_50_20160219_00027.jpg



A pipe was found on the waterside toe of the levee looking upstream.

LM Start	2.75	Rating **	N	Issue No.	14
LM End	2.75	Issue Type +	Ma	Location *	LS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Trim / Thin Trees			38.350041 °	38.350041 °
				-121.536853 °	-121.536853 °
DWR ID	DWR_RD0150_02_s_2012_14				
Comment Code					
T5 : Tree stumps.					
Inspector Comment					

Photo 1 of 1 : SP_2016_RD0150_16_14_20160219_00009.jpg



View of a tree stump on the landward slope.

* Location LS : Land Side N/A : Not Applicable WS : Water Side CR : Crown		** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain		+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	--	---	--	---

**Flood Control Project Maintenance
Levee Inspections**

Maintenance Issue Types Only, Levee Inspection Report By Mile - Spring 2016

Reclamation District No. 0150 Merrit Island

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 02 Sacramento River	Right	7.81	03/15/2016 03/15/2016	Pavel Kazi

LM Start	3.24	Rating **	M	Issue No.	961
LM End	3.24	Issue Type +	Ma	Location *	WS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Erosion / Bank Caving			38.355321 °	38.355321 °
				-121.530902 °	-121.530902 °
DWR ID	DWR_RD0150_02_s _ 2012_961				
Comment Code					
E2 : Schedule repair of erosion site prior to the next inspection.					
Inspector Comment					
Depressions into the waterward slope can be seen along the waterward slope at this site. Also note the damaged pump support, pump, and pipe just upstream of the site; they may contribute to the erosion in a high water event and should be removed.					

LM Start	3.24	Rating **	M	Issue No.	961 (cont)
LM End	3.24	Issue Type +	Ma	Location *	WS

Photo 1 of 5 : SP_2016_RD0150_16_961_20160219_00047.jpg



Updated picture of the erosion on the waterside of the levee during spring 2015 inspection.

Photo 2 of 5 : SP_2016_RD0150_16_961_20160219_00048.jpg



View of the erosion on the waterside slope of the levee near the pipe looking downstream. This picture was taken during the fall 2013 inspection.

* Location LS : Land Side N/A : Not Applicable WS : Water Side CR : Crown		** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain		+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement	
--	--	---	--	---	--

**Flood Control Project Maintenance
Levee Inspections**

Maintenance Issue Types Only, Levee Inspection Report By Mile - Spring 2016

Reclamation District No. 0150 Merrit Island

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 02 Sacramento River	Right	7.81	03/15/2016 03/15/2016	Pavel Kazi

LM Start	3.24	Rating **	M	Issue No.	961 (cont)
LM End	3.24	Issue Type +	Ma	Location *	WS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Erosion / Bank Caving			38.355321 °	38.355321 °
				-121.530902 °	-121.530902 °
DWR ID	DWR_RD0150_02_s_2012_961				
Comment Code					
E2 : Schedule repair of erosion site prior to the next inspection.					
Inspector Comment					
Depressions into the waterward slope can be seen along the waterward slope at this site. Also note the damaged pump support, pump, and pipe just upstream of the site; they may contribute to the erosion in a high water event and should be removed.					

Photo 3 of 5 : SP_2016_RD0150_16_961_20160219_00049.jpg



View of the erosion on the waterside slope of the levee looking upstream during spring 2013 inspection.

LM Start	3.24	Rating **	M	Issue No.	961 (cont)
LM End	3.24	Issue Type +	Ma	Location *	WS

Photo 4 of 5 : SP_2016_RD0150_16_961_20160219_00050.jpg



View of erosion and damaged pipe and abandoned boat on the waterside of the levee looking upstream. This picture was taken during fall 2012 inspection.

* Location LS : Land Side N/A : Not Applicable WS : Water Side CR : Crown		** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain		+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement	
---	--	--	--	--	--

**Flood Control Project Maintenance
Levee Inspections**

Maintenance Issue Types Only, Levee Inspection Report By Mile - Spring 2016

Reclamation District No. 0150 Merrit Island

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 02 Sacramento River	Right	7.81	03/15/2016 03/15/2016	Pavel Kazi

LM Start	3.24	Rating **	M	Issue No.	961 (cont)	
LM End	3.24	Issue Type +	Ma	Location *	WS	
Category	Earthen Levee			GPS Latitude/Longitude		
				Start		End
Item	Erosion / Bank Caving			38.355321 °		38.355321 °
				-121.530902 °		-121.530902 °
DWR ID	DWR_RD0150_02_s _ 2012_961					
Comment Code						
E2 : Schedule repair of erosion site prior to the next inspection.						
Inspector Comment						
Depressions into the waterward slope can be seen along the waterward slope at this site. Also note the damaged pump support, pump, and pipe just upstream of the site; they may contribute to the erosion in a high water event and should be removed.						

Photo 5 of 5 : SP_2016_RD0150_16_961_20160219_00051.jpg



View of the erosion site, and broken pump support along with a boat on the waterside of the levee. The picture was taken from the crown looking towards the toe of the levee during fall 2011 inspection.

LM Start	3.30	Rating **	M	Issue No.	17
LM End	3.30	Issue Type +	Ma	Location *	LS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Vegetation			38.355979 °	38.355979 °
				-121.530288 °	-121.530288 °
DWR ID	DWR_RD0150_02_s _ 2012_17				
Comment Code					
V4 : Elderberries are blocking visibility and flood fight capability.					
Inspector Comment					
Elderberry is partially blocking the visibility.					

No Photos

* Location LS : Land Side N/A : Not Applicable WS : Water Side CR : Crown		** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain		+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement	
---	--	--	--	--	--

**Flood Control Project Maintenance
Levee Inspections**

Maintenance Issue Types Only, Levee Inspection Report By Mile - Spring 2016

Reclamation District No. 0150 Merrit Island

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 02 Sacramento River	Right	7.81	03/15/2016 03/15/2016	Pavel Kazi

LM Start	3.91	Rating **	M	Issue No.	61
LM End	3.91	Issue Type +	Ma	Location *	LS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Encroachments			38.362357 °	38.362357 °
				-121.522582 °	-121.522582 °
DWR ID	DWR_RD0150_02_s _ 2016_61				
Comment Code					
PR : Prunings					
Inspector Comment					

Photo 1 of 1 : SP_2016_RD0150_16_61_20160318_00116.jpg



View of prunings on the landside of the levee.

LM Start	4.50	Rating **	A/W	Issue No.	1
LM End	4.57	Issue Type +	Ma	Location *	WS
Category	Supplemental			GPS Latitude/Longitude	
				Start	End
Item	2015 USACE Erosion Survey, DRAFT			38.370928 °	38.371909 °
				-121.523069 °	-121.523316 °
DWR ID	DWR_RD0150_02_s _ 2016_1				
Comment Code					
Inspector Comment					
1999 - Downstream end (300 ft) repaired with rock. 2010 - Toe erosion, some vertical slopes lower down. 2011 - Failing rock repair. Slumping of the lower bank. Minor new erosion. 2013 - Tree at upstream end has exposed roots. Some new erosion. 2015: No observed changes. [2015 Site ID: SAC_38-5_R]					

No Photos

LM Start	4.69	Rating **	M	Issue No.	28
LM End	4.69	Issue Type +	Ma	Location *	WS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Vegetation			38.373485 °	38.373485 °
				-121.523963 °	-121.523963 °
DWR ID	DWR_RD0150_02_s _ 2012_28				
Comment Code					
V2 : Remove the wild growth other than native grasses from the levee slopes.					
Inspector Comment					

Photo 1 of 1 : SP_2016_RD0150_16_28_20160219_00016.jpg



Century plant on waterward slope at LM 4.76

* Location		** Rating		+ Issue Type	
LS : Land Side	N/A : Not Applicable	A : Acceptable	N : Not Inspected/Rated	Ma : Maintenance Deficiency	
WS : Water Side		M : Minimally Acceptable	C : Corrected	Ob : Design & System Obsolescence	
CR : Crown		U : Unacceptable	A/W : Acceptable but Monitor & Maintain	En : Enforcement	

**Flood Control Project Maintenance
Levee Inspections**

Maintenance Issue Types Only, Levee Inspection Report By Mile - Spring 2016

Reclamation District No. 0150 Merrit Island

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 02 Sacramento River	Right	7.81	03/15/2016 03/15/2016	Pavel Kazi

LM Start	5.06	Rating **	A/W	Issue No.	40
LM End	7.81	Issue Type +	Ma	Location *	WS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Vegetation			38.378674 °	38.414029 °
				-121.525423 °	-121.522991 °
DWR ID	DWR_RD0150_02_s_2012_40				
Comment Code					
V8 : Environmental Requirements.					
Inspector Comment					

No Photos

LM Start	5.24	Rating **	M	Issue No.	975
LM End	5.24	Issue Type +	Ma	Location *	WS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Slope Stability			38.381126 °	38.381126 °
				-121.524207 °	-121.524207 °
DWR ID	DWR_RD0150_02_s_2013_975				
Comment Code					
S1 : Repair slope instability.					
Inspector Comment					
Depression in the waterward slope at the shoulder over an irrigation pipe.					

Photo 1 of 2 : SP_2016_RD0150_16_975_20160219_00052.jpg



View of minor slope instability on the waterside slope of the levee looking downstream during fall 2013 inspection.

LM Start	5.24	Rating **	M	Issue No.	975 (cont)
LM End	5.24	Issue Type +	Ma	Location *	WS

Photo 2 of 2 : SP_2016_RD0150_16_975_20160219_00053.jpg



View of a minor depression along the landward slope of the levee over a pipe penetration looking downstream.

* Location		** Rating		+ Issue Type	
LS : Land Side	N/A : Not Applicable	A : Acceptable	N : Not Inspected/Rated	Ma : Maintenance Deficiency	
WS : Water Side		M : Minimally Acceptable	C : Corrected	Ob : Design & System Obsolescence	
CR : Crown		U : Unacceptable	A/W : Acceptable but Monitor & Maintain	En : Enforcement	

**Flood Control Project Maintenance
Levee Inspections**

Maintenance Issue Types Only, Levee Inspection Report By Mile - Spring 2016

Reclamation District No. 0150 Merrit Island

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 02 Sacramento River	Right	7.81	03/15/2016 03/15/2016	Pavel Kazi

LM Start	5.31	Rating **	C	Issue No.	47
LM End	5.31	Issue Type +	Ma	Location *	WS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Encroachments			38.381894 °	38.381894 °
				-121.523527 °	-121.523527 °
DWR ID	DWR_RD0150_02_f_2015_47				
Comment Code					
TR : Tree or limb					
Inspector Comment					
Tree trunk on waterside toe might damage the levee during high water.					

No Photos

LM Start	5.33	Rating **	M	Issue No.	54
LM End	5.33	Issue Type +	Ma	Location *	WS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Slope Stability			38.382072 °	38.382072 °
				-121.523220 °	-121.523220 °
DWR ID	DWR_RD0150_02_f_2014_54				
Comment Code					
S2 : Repair the levee slope damaged by foot traffic and prevent access where possible.					
Inspector Comment					

Photo 1 of 1 : SP_2016_RD0150_16_54_20160219_00029.jpg



View of a slope instability on the waterside of the levee looking towards the toe.

* Location LS : Land Side N/A : Not Applicable WS : Water Side CR : Crown		** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain		+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	--	---	--	---

**Flood Control Project Maintenance
Levee Inspections**

Maintenance Issue Types Only, Levee Inspection Report By Mile - Spring 2016

Reclamation District No. 0150 Merrit Island

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 02 Sacramento River	Right	7.81	03/15/2016 03/15/2016	Pavel Kazi

LM Start	6.50	Rating **	U	Issue No.	55
LM End	6.50	Issue Type +	Ma	Location *	WS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Encroachments			38.396518 °	38.396518 °
				-121.514530 °	-121.514530 °
DWR ID	DWR_RD0150_02_f_2014_55				
Comment Code					
PI : Pipe					
Inspector Comment					
The pipe gate needs to be covered on the waterside toe of the levee.					

Photo 1 of 1 : SP_2016_RD0150_16_55_20160219_00030.jpg



An open pipe valve was found without a cover on the waterside toe of the levee.

LM Start	7.22	Rating **	M	Issue No.	32
LM End	7.22	Issue Type +	Ma	Location *	LS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Vegetation			38.406454 °	38.406454 °
				-121.517732 °	-121.517732 °
DWR ID	DWR_RD0150_02_s_2012_32				
Comment Code					
V4 : Elderberries are blocking visibility and flood fight capability.					
Inspector Comment					

No Photos

* Location LS : Land Side N/A : Not Applicable WS : Water Side CR : Crown		** Rating A : Acceptable N : Not Inspected/Rated M : Minimally Acceptable C : Corrected U : Unacceptable A/W : Acceptable but Monitor & Maintain		+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	--	---	--	---

**Flood Control Project Maintenance
Levee Inspections**

Maintenance Issue Types Only, Levee Inspection Report By Mile - Spring 2016

Reclamation District No. 0150 Merrit Island

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 03 Elk Slough	Left	9.41	03/16/2016 03/16/2016	Pavel Kazi

LM Start	0.11	Rating **	M	Issue No.	936
LM End	0.11	Issue Type +	Ma	Location *	WS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Vegetation			38.334233 °	38.334233 °
				-121.583414 °	-121.583414 °
DWR ID	DWR_RD0150_03_s_2012_936				
Comment Code					
V4 : Elderberries are blocking visibility and flood fight capability.					
Inspector Comment					
Elderberries are partially blocking visibility.					

Photo 1 of 1 : SP_2016_RD0150_17_936_20160219_00097.jpg



View of elderberry bush within 20 feet of shoulder blocking visibility and access.

LM Start	0.41	Rating **	M	Issue No.	76
LM End	2.33	Issue Type +	Ma	Location *	LS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Vegetation			38.338311 °	38.354484 °
				-121.581394 °	-121.564198 °
DWR ID	DWR_RD0150_03_s_2016_76				
Comment Code					
V1 : Control annual grass and weeds on the levee slopes and easements.					
Inspector Comment					

Photo 1 of 1 : SP_2016_RD0150_17_76_20160321_00142.jpg



View of the vegetation on the landside of the levee.

LM Start	0.41	Rating **	M	Issue No.	74
LM End	2.33	Issue Type +	Ma	Location *	WS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Vegetation			38.338311 °	38.354485 °
				-121.581394 °	-121.564199 °
DWR ID	DWR_RD0150_03_s_2016_74				
Comment Code					
V1 : Control annual grass and weeds on the levee slopes and easements.					
Inspector Comment					

Photo 1 of 1 : SP_2016_RD0150_17_74_20160321_00143.jpg



View of the vegetation on the waterside of the levee.

* Location		** Rating		+ Issue Type	
LS : Land Side	N/A : Not Applicable	A : Acceptable	N : Not Inspected/Rated	Ma : Maintenance Deficiency	
WS : Water Side		M : Minimally Acceptable	C : Corrected	Ob : Design & System Obsolescence	
CR : Crown		U : Unacceptable	A/W : Acceptable but Monitor & Maintain	En : Enforcement	

**Flood Control Project Maintenance
Levee Inspections**

Maintenance Issue Types Only, Levee Inspection Report By Mile - Spring 2016

Reclamation District No. 0150 Merrit Island

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 03 Elk Slough	Left	9.41	03/16/2016 03/16/2016	Pavel Kazi

LM Start	0.59	Rating **	C	Issue No.	54
LM End	0.59	Issue Type +	Ma	Location *	LS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Animal Control			38.340741 °	38.340741 °
				-121.580797 °	-121.580797 °
DWR ID	DWR_RD0150_03_f _ 2014_54				
Comment Code					
A3 : No rodents visible, but rodent burrows visible; need to backfill and compact or grout burrows.					
Inspector Comment					

No Photos

LM Start	0.61	Rating **	C	Issue No.	390
LM End	0.61	Issue Type +	Ma	Location *	LS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Animal Control			38.341056 °	38.341056 °
				-121.580676 °	-121.580676 °
DWR ID	DWR_RD0150_03_s_2015_390				
Comment Code					
A3 : No rodents visible, but rodent burrows visible; need to backfill and compact or grout burrows.					
Inspector Comment					

No Photos

LM Start	0.92	Rating **	M	Issue No.	5
LM End	0.92	Issue Type +	Ma	Location *	LS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Vegetation			38.345493 °	38.345493 °
				-121.579682 °	-121.579682 °
DWR ID	DWR_RD0150_03_s_2012_5				
Comment Code					
V4 : Elderberries are blocking visibility and flood fight capability.					
Inspector Comment					
Elderberries are partially blocking visibility.					

Photo 1 of 1 : SP_2016_RD0150_17_5_20160219_00005.jpg



View of elderberries on the landward slope of the levee.

* Location		** Rating		+ Issue Type	
LS : Land Side	N/A : Not Applicable	A : Acceptable	N : Not Inspected/Rated	Ma : Maintenance Deficiency	
WS : Water Side		M : Minimally Acceptable	C : Corrected	Ob : Design & System Obsolescence	
CR : Crown		U : Unacceptable	A/W : Acceptable but Monitor & Maintain	En : Enforcement	

**Flood Control Project Maintenance
Levee Inspections**

Maintenance Issue Types Only, Levee Inspection Report By Mile - Spring 2016

Reclamation District No. 0150 Merrit Island

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 03 Elk Slough	Left	9.41	03/16/2016 03/16/2016	Pavel Kazi

LM Start	1.40	Rating **	M	Issue No.	393
LM End	1.40	Issue Type +	Ma	Location *	WS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Animal Control			38.347880 °	38.347880 °
				-121.572500 °	-121.572500 °
DWR ID	DWR_RD0150_03_s_2015_393				
Comment Code					
A3 : No rodents visible, but rodent burrows visible; need to backfill and compact or grout burrows.					
Inspector Comment					

Photo 1 of 1 : SP_2016_RD0150_17_393_20160219_00091.jpg



Rodent holes were found on the waterside of the levee looking downstream.

LM Start	1.78	Rating **	M	Issue No.	50
LM End	1.78	Issue Type +	Ma	Location *	WS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Erosion / Bank Caving			38.353249 °	38.353249 °
				-121.572848 °	-121.572848 °
DWR ID	DWR_RD0150_03_s_2012_50				
Comment Code					
E1 : Note and monitor erosion site.					
Inspector Comment					
Erosion appeared under the pipe.					

Photo 1 of 1 : SP_2016_RD0150_17_50_20160219_00043.jpg



Steps were dug next to the pipe and also erosion was found near the vicinity of the pipe on the waterside slope of the levee looking upstream.

* Location LS : Land Side N/A : Not Applicable WS : Water Side CR : Crown		** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain		+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement	
---	--	--	--	--	--

**Flood Control Project Maintenance
Levee Inspections**

Maintenance Issue Types Only, Levee Inspection Report By Mile - Spring 2016

Reclamation District No. 0150 Merrit Island

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 03 Elk Slough	Left	9.41	03/16/2016 03/16/2016	Pavel Kazi

LM Start	1.83	Rating **	M	Issue No.	85
LM End	1.83	Issue Type +	Ma	Location *	WS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Encroachments			38.353761 °	38.353761 °
				-121.572390 °	-121.572390 °
DWR ID	DWR_RD0150_03_s_2016_85				
Comment Code					
TR : Tree or limb					
Inspector Comment					

Photo 1 of 1 : SP_2016_RD0150_17_85_20160321_00144.jpg



View of broken tree trunk on the waterside slope of the levee.

LM Start	2.24	Rating **	M	Issue No.	75
LM End	2.24	Issue Type +	Ma	Location *	LS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Vegetation			38.353811 °	38.353811 °
				-121.565668 °	-121.565668 °
DWR ID	DWR_RD0150_03_f_2014_75				
Comment Code					
V2 : Remove the wild growth other than native grasses from the levee slopes.					
Inspector Comment					
Newly planted tree was found on the landside slope of the levee.					

Photo 1 of 2 : SP_2016_RD0150_17_75_20160321_00145.jpg



Updated picture of the newly planted tree on the landside shoulder of the levee during spring 2016.

LM Start	2.24	Rating **	M	Issue No.	75 (cont)
LM End	2.24	Issue Type +	Ma	Location *	LS

Photo 2 of 2 : SP_2016_RD0150_17_75_20160219_00069.jpg



View of a few trees that were planted on the landside slope of the levee looking upstream.

* Location		** Rating		+ Issue Type	
LS : Land Side	N/A : Not Applicable	A : Acceptable	N : Not Inspected/Rated	Ma : Maintenance Deficiency	
WS : Water Side		M : Minimally Acceptable	C : Corrected	Ob : Design & System Obsolescence	
CR : Crown		U : Unacceptable	A/W : Acceptable but Monitor & Maintain	En : Enforcement	

**Flood Control Project Maintenance
Levee Inspections**

Maintenance Issue Types Only, Levee Inspection Report By Mile - Spring 2016

Reclamation District No. 0150 Merrit Island

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 03 Elk Slough	Left	9.41	03/16/2016 03/16/2016	Pavel Kazi

LM Start	2.31	Rating **	M	Issue No.	78
LM End	2.31	Issue Type +	Ma	Location *	LS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Trim / Thin Trees			38.354286 °	38.354286 °
				-121.564494 °	-121.564494 °
DWR ID	DWR_RD0150_03_s_2012_78				
Comment Code					
T2 : Thin trees to allow visibility of the ground and room to flood fight.					
Inspector Comment					
New tree was planted on the landside slope.					

LM Start	2.31	Rating **	M	Issue No.	78 (cont)
LM End	2.31	Issue Type +	Ma	Location *	LS

Photo 1 of 4 : SP_2016_RD0150_17_78_20160219_00071.jpg



Updated picture of the trees on the landside of the levee during spring 2015 inspection.

Photo 2 of 4 : SP_2016_RD0150_17_78_20160219_00072.jpg



View of the newly planted tree on the landside slope of the levee during spring 2014 inspection.

* Location LS : Land Side N/A : Not Applicable WS : Water Side CR : Crown		** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain		+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	--	---	--	---

**Flood Control Project Maintenance
Levee Inspections**

Maintenance Issue Types Only, Levee Inspection Report By Mile - Spring 2016

Reclamation District No. 0150 Merrit Island

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 03 Elk Slough	Left	9.41	03/16/2016 03/16/2016	Pavel Kazi

LM Start	2.31	Rating **	M	Issue No.	78 (cont)	
LM End	2.31	Issue Type +	Ma	Location *	LS	
Category	Earthen Levee			GPS Latitude/Longitude		
				Start		End
Item	Trim / Thin Trees			38.354286 °		38.354286 °
				-121.564494 °		-121.564494 °
DWR ID	DWR_RD0150_03_s_2012_78					
Comment Code						
T2 : Thin trees to allow visibility of the ground and room to flood fight.						
Inspector Comment						
New tree was planted on the landside slope.						

LM Start	2.31	Rating **	M	Issue No.	78 (cont)
LM End	2.31	Issue Type +	Ma	Location *	LS

Photo 3 of 4 : SP_2016_RD0150_17_78_20160219_00073.jpg



Several newly planted trees were found on the landside slope of the levee looking upstream during the fall 2013 inspection.

Photo 4 of 4 : SP_2016_RD0150_17_78_20160219_00074.jpg



New tree was planted on the landside of the levee looking downstream.

LM Start	2.55	Rating **	N	Issue No.	11
LM End	2.55	Issue Type +	Ma	Location *	LS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Trim / Thin Trees			38.356853 °	38.356853 °
				-121.561565 °	-121.561565 °
DWR ID	DWR_RD0150_03_s_2012_11				
Comment Code					
T5 : Tree stumps.					
Inspector Comment					

Photo 1 of 1 : SP_2016_RD0150_17_11_20160219_00008.jpg



View of tree stumps on the landward slope.

* Location		** Rating		+ Issue Type	
LS : Land Side	N/A : Not Applicable	A : Acceptable	N : Not Inspected/Rated	Ma : Maintenance Deficiency	
WS : Water Side		M : Minimally Acceptable	C : Corrected	Ob : Design & System Obsolescence	
CR : Crown		U : Unacceptable	A/W : Acceptable but Monitor & Maintain	En : Enforcement	

**Flood Control Project Maintenance
Levee Inspections**

Maintenance Issue Types Only, Levee Inspection Report By Mile - Spring 2016

Reclamation District No. 0150 Merrit Island

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 03 Elk Slough	Left	9.41	03/16/2016 03/16/2016	Pavel Kazi

LM Start	2.65	Rating **	M	Issue No.	86
LM End	2.65	Issue Type +	Ma	Location *	WS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Encroachments			38.358228 °	38.358228 °
				-121.561316 °	-121.561316 °
DWR ID	DWR_RD0150_03_s_2016_86				
Comment Code					
DE : Debris					
Inspector Comment					

Photo 1 of 1 : SP_2016_RD0150_17_86_20160321_00146.jpg



View of the debris on the waterside slope of the levee.

LM Start	2.80	Rating **	M	Issue No.	35
LM End	2.80	Issue Type +	Ma	Location *	WS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Erosion / Bank Caving			38.360432 °	38.360432 °
				-121.561644 °	-121.561644 °
DWR ID	DWR_RD0150_03_s_2013_35				
Comment Code					
E2 : Schedule repair of erosion site prior to the next inspection.					
Inspector Comment					

Photo 1 of 2 : SP_2016_RD0150_17_35_20160219_00028.jpg



Updated picture of the erosion on the waterside of the levee during spring 2015 inspection.

LM Start	2.80	Rating **	M	Issue No.	35 (cont)
LM End	2.80	Issue Type +	Ma	Location *	WS

Photo 2 of 2 : SP_2016_RD0150_17_35_20160219_00029.jpg



Updated picture of the erosion on the waterside slope of the levee during spring 2014 inspection.

* Location		** Rating		+ Issue Type	
LS : Land Side	N/A : Not Applicable	A : Acceptable	N : Not Inspected/Rated	Ma : Maintenance Deficiency	
WS : Water Side		M : Minimally Acceptable	C : Corrected	Ob : Design & System Obsolescence	
CR : Crown		U : Unacceptable	A/W : Acceptable but Monitor & Maintain	En : Enforcement	

**Flood Control Project Maintenance
Levee Inspections**

Maintenance Issue Types Only, Levee Inspection Report By Mile - Spring 2016

Reclamation District No. 0150 Merrit Island

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 03 Elk Slough	Left	9.41	03/16/2016 03/16/2016	Pavel Kazi

LM Start	2.82	Rating **	N	Issue No.	17
LM End	2.82	Issue Type +	Ma	Location *	WS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Trim / Thin Trees			38.360621 °	38.360621 °
				-121.561762 °	-121.561762 °
DWR ID	DWR_RD0150_03_s_2012_17				
Comment Code					
T5 : Tree stumps.					
Inspector Comment					

Photo 1 of 1 : SP_2016_RD0150_17_17_20160219_00015.jpg



View of tree stumps on the waterward slope.

LM Start	3.15	Rating **	N	Issue No.	20	
LM End	3.15	Issue Type +	Ma	Location *	WS	
Category	Earthen Levee			GPS Latitude/Longitude		
				Start		End
Item	Trim / Thin Trees			38.363658 °		38.363658 °
				-121.559583 °		-121.559583 °
DWR ID	DWR_RD0150_03_s_2012_20					
Comment Code						
T5 : Tree stumps.						
Inspector Comment						

Photo 1 of 1 : SP_2016_RD0150_17_20_20160219_00016.jpg



View of tree stumps on the waterward slope.

LM Start	3.20	Rating **	M	Issue No.	77
LM End	3.20	Issue Type +	Ma	Location *	WS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Animal Control			38.363364 °	38.363364 °
				-121.558682 °	-121.558682 °
DWR ID	DWR_RD0150_03_f_2014_77				
Comment Code					
A3 : No rodents visible, but rodent burrows visible; need to backfill and compact or grout burrows.					
Inspector Comment					

Photo 1 of 1 : SP_2016_RD0150_17_77_20160219_00070.jpg



A rodent hole was found on the waterside of the levee looking upstream.

*** Location**
LS : Land Side N/A : Not Applicable
WS : Water Side
CR : Crown

**** Rating**
A : Acceptable N : Not Inspected/Rated
M : Minimally Acceptable C : Corrected
U : Unacceptable A/W : Acceptable but Monitor & Maintain

+ Issue Type
Ma : Maintenance Deficiency
Ob : Design & System Obsolescence
En : Enforcement

**Flood Control Project Maintenance
Levee Inspections**

Maintenance Issue Types Only, Levee Inspection Report By Mile - Spring 2016

Reclamation District No. 0150 Merrit Island

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 03 Elk Slough	Left	9.41	03/16/2016 03/16/2016	Pavel Kazi

LM Start	3.31	Rating **	M	Issue No.	40
LM End	3.31	Issue Type +	Ma	Location *	WS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Erosion / Bank Caving			38.363008 °	38.363008 °
				-121.556751 °	-121.556751 °
DWR ID	DWR_RD0150_03_s_2013_40				
Comment Code					
E2 : Schedule repair of erosion site prior to the next inspection.					
Inspector Comment					

LM Start	3.31	Rating **	M	Issue No.	40 (cont)
LM End	3.31	Issue Type +	Ma	Location *	WS

Photo 1 of 2 : SP_2016_RD0150_17_40_20160219_00033.jpg



Updated picture of the erosion on the waterside of the levee during spring 2015 inspection.

Photo 2 of 2 : SP_2016_RD0150_17_40_20160219_00034.jpg



Updated picture of the erosion on the waterside of the levee looking upstream during fall 2014 inspection.

* Location LS : Land Side N/A : Not Applicable WS : Water Side CR : Crown		** Rating A : Acceptable N : Not Inspected/Rated M : Minimally Acceptable C : Corrected U : Unacceptable A/W : Acceptable but Monitor & Maintain		+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	--	---	--	---

**Flood Control Project Maintenance
Levee Inspections**

Maintenance Issue Types Only, Levee Inspection Report By Mile - Spring 2016

Reclamation District No. 0150 Merrit Island

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 03 Elk Slough	Left	9.41	03/16/2016 03/16/2016	Pavel Kazi

LM Start	3.34	Rating **	N	Issue No.	27
LM End	3.34	Issue Type +	Ma	Location *	WS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Trim / Thin Trees			38.363147 °	38.363147 °
				-121.556190 °	-121.556190 °
DWR ID	DWR_RD0150_03_s_2012_27				
Comment Code					
T5 : Tree stumps.					
Inspector Comment					

Photo 1 of 1 : SP_2016_RD0150_17_27_20160219_00020.jpg



View of tree stumps on the waterside slope looking upstream.

LM Start	3.39	Rating **	M	Issue No.	114
LM End	3.39	Issue Type +	Ma	Location *	WS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Encroachments			38.363540 °	38.363540 °
				-121.555555 °	-121.555555 °
DWR ID	DWR_RD0150_03_f_2013_114				
Comment Code					
ST : Stairway					
Inspector Comment					

Photo 1 of 1 : SP_2016_RD0150_17_114_20160219_00087.jpg



View of steps that were dug on the waterside slope of the levee looking upstream.

* Location LS : Land Side N/A : Not Applicable WS : Water Side CR : Crown		** Rating A : Acceptable N : Not Inspected/Rated M : Minimally Acceptable C : Corrected U : Unacceptable A/W : Acceptable but Monitor & Maintain		+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	--	---	--	---

**Flood Control Project Maintenance
Levee Inspections**

Maintenance Issue Types Only, Levee Inspection Report By Mile - Spring 2016

Reclamation District No. 0150 Merrit Island

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 03 Elk Slough	Left	9.41	03/16/2016 03/16/2016	Pavel Kazi

LM Start	3.39	Rating **	U	Issue No.	115
LM End	3.39	Issue Type +	Ma	Location *	LS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Erosion / Bank Caving			38.363540 °	38.363540 °
				-121.555554 °	-121.555554 °
DWR ID	DWR_RD0150_03_f_2013_115				
Comment Code					
E2 : Schedule repair of erosion site prior to the next inspection.					
Inspector Comment					
Erosion (ditch) was found on the landside toe of the levee.					

LM Start	3.39	Rating **	U	Issue No.	115 (cont)
LM End	3.39	Issue Type +	Ma	Location *	LS

Photo 1 of 2 : SP_2016_RD0150_17_115_20160219_00088.jpg



Updated picture of the ditch on the landside toe of the levee during fall 2015 inspection.

Photo 2 of 2 : SP_2016_RD0150_17_115_20160219_00089.jpg



A drainage ditch with depth of 4 feet and width of 15 feet was found on the landside toe of the levee. The picture was taken from the landside slope looking upstream during the fall 2013 inspection.

* Location LS : Land Side N/A : Not Applicable WS : Water Side CR : Crown		** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain		+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement	
---	--	--	--	--	--

**Flood Control Project Maintenance
Levee Inspections**

Maintenance Issue Types Only, Levee Inspection Report By Mile - Spring 2016

Reclamation District No. 0150 Merrit Island

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 03 Elk Slough	Left	9.41	03/16/2016 03/16/2016	Pavel Kazi

LM Start	3.41	Rating **	U	Issue No.	98
LM End	3.41	Issue Type +	Ma	Location *	WS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Erosion / Bank Caving			38.363803 °	38.363803 °
				-121.555432 °	-121.555432 °
DWR ID	DWR_RD0150_03_s_2012_98				
Comment Code					
E1 : Note and monitor erosion site.					
Inspector Comment					
Erosion was located on the waterside of the levee looking downstream.					

Photo 1 of 1 : SP_2016_RD0150_17_98_20160219_00086.jpg



Erosion was found on the waterside of the levee looking downstream.

LM Start	3.51	Rating **	M	Issue No.	42
LM End	3.51	Issue Type +	Ma	Location *	WS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Animal Control			38.365259 °	38.365259 °
				-121.555429 °	-121.555429 °
DWR ID	DWR_RD0150_03_f_2015_42				
Comment Code					
A3 : No rodents visible, but rodent burrows visible; need to backfill and compact or grout burrows.					
Inspector Comment					

Photo 1 of 1 : SP_2016_RD0150_17_42_20160219_00035.jpg



View of a rodent hole on the waterside of the levee.

LM Start	3.72	Rating **	C	Issue No.	45
LM End	3.72	Issue Type +	Ma	Location *	WS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Animal Control			38.367381 °	38.367381 °
				-121.554102 °	-121.554102 °
DWR ID	DWR_RD0150_03_f_2015_45				
Comment Code					
A3 : No rodents visible, but rodent burrows visible; need to backfill and compact or grout burrows.					
Inspector Comment					

No Photos

* Location LS : Land Side N/A : Not Applicable WS : Water Side CR : Crown		** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable		+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement	
		N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain			

**Flood Control Project Maintenance
Levee Inspections**

Maintenance Issue Types Only, Levee Inspection Report By Mile - Spring 2016

Reclamation District No. 0150 Merrit Island

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 03 Elk Slough	Left	9.41	03/16/2016 03/16/2016	Pavel Kazi

LM Start	3.79	Rating **	M	Issue No.	116
LM End	3.79	Issue Type +	Ma	Location *	WS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Slope Stability			38.367535 °	38.367535 °
				-121.552815 °	-121.552815 °
DWR ID	DWR_RD0150_03_f_2013_116				
Comment Code					
S1 : Repair slope instability.					
Inspector Comment					

No Photos

LM Start	3.99	Rating **	M	Issue No.	91
LM End	9.32	Issue Type +	Ma	Location *	LS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Vegetation			38.369707 °	38.412986 °
				-121.551756 °	-121.524148 °
DWR ID	DWR_RD0150_03_s_2016_91				
Comment Code					
V1 : Control annual grass and weeds on the levee slopes and easements.					
Inspector Comment					

No Photos

LM Start	4.02	Rating **	M	Issue No.	93
LM End	4.02	Issue Type +	Ma	Location *	WS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Erosion / Bank Caving			38.370125 °	38.370125 °
				-121.552030 °	-121.552030 °
DWR ID	DWR_RD0150_03_s_2016_93				
Comment Code					
E1 : Note and monitor erosion site.					
Inspector Comment					
Erosion on the waterside toe of the levee.					

Photo 1 of 1 : SP_2016_RD0150_17_93_20160321_00147.jpg



An erosion was found on the waterside toe of the levee.

* Location		** Rating		+ Issue Type	
LS : Land Side	N/A : Not Applicable	A : Acceptable	N : Not Inspected/Rated	Ma : Maintenance Deficiency	
WS : Water Side		M : Minimally Acceptable	C : Corrected	Ob : Design & System Obsolescence	
CR : Crown		U : Unacceptable	A/W : Acceptable but Monitor & Maintain	En : Enforcement	

**Flood Control Project Maintenance
Levee Inspections**

Maintenance Issue Types Only, Levee Inspection Report By Mile - Spring 2016

Reclamation District No. 0150 Merrit Island

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 03 Elk Slough	Left	9.41	03/16/2016 03/16/2016	Pavel Kazi

LM Start	4.28	Rating **	C	Issue No.	37
LM End	4.28	Issue Type +	Ma	Location *	WS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Trim / Thin Trees			38.373319 °	38.373319 °
				-121.550836 °	-121.550836 °
DWR ID	DWR_RD0150_03_s_2012_37				
Comment Code					
T5 : Tree stumps.					
Inspector Comment					

No Photos

LM Start	4.49	Rating **	U	Issue No.	80
LM End	4.49	Issue Type +	Ma	Location *	WS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Erosion / Bank Caving			38.374355 °	38.374355 °
				-121.547436 °	-121.547436 °
DWR ID	DWR_RD0150_03_s_2014_80				
Comment Code					
E2 : Schedule repair of erosion site prior to the next inspection.					
Inspector Comment					

Photo 1 of 1 : SP_2016_RD0150_17_80_20160219_00075.jpg



View of an erosion site on the waterside toe of the levee looking upstream.

* Location LS : Land Side N/A : Not Applicable WS : Water Side CR : Crown		** Rating A : Acceptable N : Not Inspected/Rated M : Minimally Acceptable C : Corrected U : Unacceptable A/W : Acceptable but Monitor & Maintain		+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	--	---	--	---

**Flood Control Project Maintenance
Levee Inspections**

Maintenance Issue Types Only, Levee Inspection Report By Mile - Spring 2016

Reclamation District No. 0150 Merrit Island

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 03 Elk Slough	Left	9.41	03/16/2016 03/16/2016	Pavel Kazi

LM Start	4.99	Rating **	M	Issue No.	36
LM End	4.99	Issue Type +	Ma	Location *	WS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Slope Stability			38.378771 °	38.378771 °
				-121.540538 °	-121.540538 °
DWR ID	DWR_RD0150_03_f_2012_36				
Comment Code					
S1 : Repair slope instability.					
Inspector Comment					

LM Start	4.99	Rating **	M	Issue No.	36 (cont)
LM End	4.99	Issue Type +	Ma	Location *	WS

Photo 1 of 2 : SP_2016_RD0150_17_36_20160219_00030.jpg



Updated picture of the slope instability of the waterside shoulder of the levee during fall 2015 inspection.

Photo 2 of 2 : SP_2016_RD0150_17_36_20160219_00031.jpg



Slope instability was found on the waterside of the levee looking upstream.

* Location LS : Land Side N/A : Not Applicable WS : Water Side CR : Crown		** Rating A : Acceptable N : Not Inspected/Rated M : Minimally Acceptable C : Corrected U : Unacceptable A/W : Acceptable but Monitor & Maintain		+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	--	---	--	---

**Flood Control Project Maintenance
Levee Inspections**

Maintenance Issue Types Only, Levee Inspection Report By Mile - Spring 2016

Reclamation District No. 0150 Merrit Island

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 03 Elk Slough	Left	9.41	03/16/2016 03/16/2016	Pavel Kazi

LM Start	5.14	Rating **	M	Issue No.	941
LM End	5.14	Issue Type +	Ma	Location *	CR
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Crown Surface / Depressions / Rutting			38.380779 °	38.380779 °
				-121.540264 °	-121.540264 °
DWR ID	DWR_RD0150_03_s_2012_941				
Comment Code					
C2 : Repair depressions or ruts in the crown or slope.					
Inspector Comment					
There is a significant difference in the crown roadway elevation as it transitions from the paved roadway to the gravel access road.					

Photo 1 of 1 : SP_2016_RD0150_17_941_20160219_00098.jpg



View of varying elevations in the crown of the levee at the transition from county road to access road.

LM Start	5.32	Rating **	M	Issue No.	96	
LM End	5.32	Issue Type +	Ma	Location *	WS	
Category	Earthen Levee			GPS Latitude/Longitude		
				Start		End
Item	Encroachments			38.381843 °		38.381843 °
				-121.543117 °		-121.543117 °
DWR ID	DWR_RD0150_03_s_2016_96					
Comment Code						
TR : Tree or limb						
Inspector Comment						
Broken tree/root damaged levee slope.						

Photo 1 of 1 : SP_2016_RD0150_17_96_20160321_00149.jpg



Broken tree roots and tree trunks were found on the waterside toe of the levee.

* Location		** Rating		+ Issue Type	
LS : Land Side	N/A : Not Applicable	A : Acceptable	N : Not Inspected/Rated	Ma : Maintenance Deficiency	
WS : Water Side		M : Minimally Acceptable	C : Corrected	Ob : Design & System Obsolescence	
CR : Crown		U : Unacceptable	A/W : Acceptable but Monitor & Maintain	En : Enforcement	

**Flood Control Project Maintenance
Levee Inspections**

Maintenance Issue Types Only, Levee Inspection Report By Mile - Spring 2016

Reclamation District No. 0150 Merrit Island

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 03 Elk Slough	Left	9.41	03/16/2016 03/16/2016	Pavel Kazi

LM Start	5.56	Rating **	N	Issue No.	68
LM End	5.56	Issue Type +	Ma	Location *	WS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Trim / Thin Trees			38.383697 °	38.383697 °
				-121.545201 °	-121.545201 °
DWR ID	DWR_RD0150_03_s _ 2012_68				
Comment Code					
T5 : Tree stumps.					
Inspector Comment					

Photo 1 of 1 : SP_2016_RD0150_17_68_20160219_00067.jpg



Tree stump was found on the waterside of the levee looking upstream.

LM Start	5.69	Rating **	N	Issue No.	41
LM End	5.69	Issue Type +	Ma	Location *	WS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Trim / Thin Trees			38.383969 °	38.383969 °
				-121.542806 °	-121.542806 °
DWR ID	DWR_RD0150_03_s _2012_41				
Comment Code					
T5 : Tree stumps.					
Inspector Comment					

No Photos

LM Start	5.78	Rating **	M	Issue No.	28
LM End	5.78	Issue Type +	Ma	Location *	WS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Vegetation			38.384333 °	38.384333 °
				-121.541310 °	-121.541310 °
DWR ID	DWR_RD0150_03_s _ 2012_28				
Comment Code					
V2 : Remove the wild growth other than native grasses from the levee slopes.					
Inspector Comment					

Photo 1 of 1 : SP_2016_RD0150_17_28_20160219_00021.jpg



Wild growth was found on the waterside slope of the levee looking upstream.

* Location		** Rating		+ Issue Type	
LS : Land Side	N/A : Not Applicable	A : Acceptable	N : Not Inspected/Rated	Ma : Maintenance Deficiency	
WS : Water Side		M : Minimally Acceptable	C : Corrected	Ob : Design & System Obsolescence	
CR : Crown		U : Unacceptable	A/W : Acceptable but Monitor & Maintain	En : Enforcement	

**Flood Control Project Maintenance
Levee Inspections**

Maintenance Issue Types Only, Levee Inspection Report By Mile - Spring 2016

Reclamation District No. 0150 Merrit Island

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 03 Elk Slough	Left	9.41	03/16/2016 03/16/2016	Pavel Kazi

LM Start	5.82	Rating **	M	Issue No.	57
LM End	5.82	Issue Type +	Ma	Location *	LS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Encroachments			38.384648 °	38.384648 °
				-121.540669 °	-121.540669 °
DWR ID	DWR_RD0150_03_s_2012_57				
Comment Code					
TR : Tree or limb					
Inspector Comment					

Photo 1 of 1 : SP_2016_RD0150_17_57_20160219_00053.jpg



View of a tree trunk lying on the landward slope blocking visibility.

LM Start	5.95	Rating **	M	Issue No.	33
LM End	5.95	Issue Type +	Ma	Location *	WS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Trim / Thin Trees			38.386351 °	38.386351 °
				-121.539828 °	-121.539828 °
DWR ID	DWR_RD0150_03_s_2012_33				
Comment Code					
T2 : Thin trees to allow visibility of the ground and room to flood fight.					
Inspector Comment					

Photo 1 of 1 : SP_2016_RD0150_17_33_20160219_00026.jpg



Tree trunks and vegetation was obstructing the visibility on the waterside slope of the levee looking downstream.

* Location LS : Land Side N/A : Not Applicable WS : Water Side CR : Crown		** Rating A : Acceptable N : Not Inspected/Rated M : Minimally Acceptable C : Corrected U : Unacceptable A/W : Acceptable but Monitor & Maintain		+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	--	---	--	---

**Flood Control Project Maintenance
Levee Inspections**

Maintenance Issue Types Only, Levee Inspection Report By Mile - Spring 2016

Reclamation District No. 0150 Merrit Island

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 03 Elk Slough	Left	9.41	03/16/2016 03/16/2016	Pavel Kazi

LM Start	5.96	Rating **	M	Issue No.	46
LM End	5.96	Issue Type +	Ma	Location *	WS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Encroachments			38.386422 °	38.386422 °
				-121.539861 °	-121.539861 °
DWR ID	DWR_RD0150_03_s_2012_46				
Comment Code					
PI : Pipe					
Inspector Comment					
Improperly abandoned pipe through the levee.					

Photo 1 of 1 : SP_2016_RD0150_17_46_20160219_00039.jpg



View of an improperly abandoned pipe through the levee looking upstream.

LM Start	6.23	Rating **	N	Issue No.	49
LM End	6.23	Issue Type +	Ma	Location *	WS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Trim / Thin Trees			38.389658 °	38.389658 °
				-121.541518 °	-121.541518 °
DWR ID	DWR_RD0150_03_s_2012_49				
Comment Code					
T5 : Tree stumps.					
Inspector Comment					

Photo 1 of 1 : SP_2016_RD0150_17_49_20160219_00042.jpg



View of tree stumps on the waterward slope.

* Location LS : Land Side N/A : Not Applicable WS : Water Side CR : Crown		** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain		+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement	
---	--	--	--	--	--

**Flood Control Project Maintenance
Levee Inspections**

Maintenance Issue Types Only, Levee Inspection Report By Mile - Spring 2016

Reclamation District No. 0150 Merrit Island

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 03 Elk Slough	Left	9.41	03/16/2016 03/16/2016	Pavel Kazi

LM Start	6.38	Rating **	U	Issue No.	62
LM End	6.38	Issue Type +	Ma	Location *	WS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Trim / Thin Trees			38.390935 °	38.390935 °
				-121.539369 °	-121.539369 °
DWR ID	DWR_RD0150_03_s_2012_62				
Comment Code					
T3 : Trim and thin trees to allow visibility of the ground and room to flood fight.					
Inspector Comment					

LM Start	6.38	Rating **	U	Issue No.	62 (cont)
LM End	6.38	Issue Type +	Ma	Location *	WS

Photo 1 of 2 : SP_2016_RD0150_17_62_20160219_00059.jpg



Tree was blocking the visibility on the waterside of the levee looking upstream. This picture was taken during fall 2012 inspection.

Photo 2 of 2 : SP_2016_RD0150_17_62_20160219_00060.jpg



Vegetation on the waterside of the levee looking downstream.

LM Start	6.90	Rating **	M	Issue No.	61
LM End	6.90	Issue Type +	Ma	Location *	WS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Erosion / Bank Caving			38.396655 °	38.396655 °
				-121.535485 °	-121.535485 °
DWR ID	DWR_RD0150_03_s_2012_61				
Comment Code					
E1 : Note and monitor erosion site.					
Inspector Comment					

Photo 1 of 2 : SP_2016_RD0150_17_61_20160219_00057.jpg



Updated picture of the erosion on the waterside of the levee during spring 2015 inspection.

* Location		** Rating		+ Issue Type	
LS : Land Side	N/A : Not Applicable	A : Acceptable	N : Not Inspected/Rated	Ma : Maintenance Deficiency	
WS : Water Side		M : Minimally Acceptable	C : Corrected	Ob : Design & System Obsolescence	
CR : Crown		U : Unacceptable	A/W : Acceptable but Monitor & Maintain	En : Enforcement	

**Flood Control Project Maintenance
Levee Inspections**

Maintenance Issue Types Only, Levee Inspection Report By Mile - Spring 2016

Reclamation District No. 0150 Merrit Island

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 03 Elk Slough	Left	9.41	03/16/2016 03/16/2016	Pavel Kazi

LM Start	6.90	Rating **	M	Issue No.	61 (cont)	
LM End	6.90	Issue Type +	Ma	Location *	WS	
Category	Earthen Levee			GPS Latitude/Longitude		
				Start		End
Item	Erosion / Bank Caving			38.396655 °		38.396655 °
				-121.535485 °		-121.535485 °
DWR ID	DWR_RD0150_03_s_2012_61					
Comment Code						
E1 : Note and monitor erosion site.						
Inspector Comment						

Photo 2 of 2 : SP_2016_RD0150_17_61_20160219_00058.jpg



Erosion was found on the waterside slope of the levee looking downstream. This updated picture was taken during fall 2012 inspection.

LM Start	6.91	Rating **	M	Issue No.	79	
LM End	6.91	Issue Type +	Ma	Location *	LS	
Category	Earthen Levee			GPS Latitude/Longitude		
				Start		End
Item	Trim / Thin Trees			38.396698 °		38.396698 °
				-121.535406 °		-121.535406 °
DWR ID	DWR_RD0150_03_f_2012_79					
Comment Code						
T2 : Thin trees to allow visibility of the ground and room to flood fight.						
Inspector Comment						

No Photos

* Location LS : Land Side N/A : Not Applicable WS : Water Side CR : Crown		** Rating A : Acceptable N : Not Inspected/Rated M : Minimally Acceptable C : Corrected U : Unacceptable A/W : Acceptable but Monitor & Maintain		+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	--	---	--	---

**Flood Control Project Maintenance
Levee Inspections**

Maintenance Issue Types Only, Levee Inspection Report By Mile - Spring 2016

Reclamation District No. 0150 Merrit Island

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 03 Elk Slough	Left	9.41	03/16/2016 03/16/2016	Pavel Kazi

LM Start	7.23	Rating **	M	Issue No.	100
LM End	9.32	Issue Type +	Ma	Location *	WS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Vegetation			38.401089 °	38.412987 °
				-121.536429 °	-121.524148 °
DWR ID	DWR_RD0150_03_s_2016_100				
Comment Code					
V1 : Control annual grass and weeds on the levee slopes and easements.					
Inspector Comment					

Photo 1 of 1 : SP_2016_RD0150_17_100_20160321_00152.jpg



View of the vegetation on the waterside slope of the levee looking upstream.

LM Start	7.38	Rating **	N	Issue No.	63
LM End	7.38	Issue Type +	Ma	Location *	LS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Trim / Thin Trees			38.402779 °	38.402779 °
				-121.538197 °	-121.538197 °
DWR ID	DWR_RD0150_03_s_2012_63				
Comment Code					
T5 : Tree stumps.					
Inspector Comment					

Photo 1 of 1 : SP_2016_RD0150_17_63_20160219_00061.jpg



View of a tree stump on the landward slope.

LM Start	7.47	Rating **	M	Issue No.	935
LM End	7.47	Issue Type +	Ma	Location *	LS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Encroachments			38.403795 °	38.403795 °
				-121.539205 °	-121.539205 °
DWR ID	DWR_RD0150_03_s_2012_935				
Comment Code					
PR : Prunings					
Inspector Comment					

Photo 1 of 2 : SP_2016_RD0150_17_935_20160219_00095.jpg



Prunings were found on the landside of the levee looking upstream.

* Location
LS : Land Side N/A : Not Applicable
WS : Water Side
CR : Crown

** Rating
A : Acceptable N : Not Inspected/Rated
M : Minimally Acceptable C : Corrected
U : Unacceptable A/W : Acceptable but Monitor & Maintain

+ Issue Type
Ma : Maintenance Deficiency
Ob : Design & System Obsolescence
En : Enforcement

**Flood Control Project Maintenance
Levee Inspections**

Maintenance Issue Types Only, Levee Inspection Report By Mile - Spring 2016

Reclamation District No. 0150 Merrit Island

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 03 Elk Slough	Left	9.41	03/16/2016 03/16/2016	Pavel Kazi

LM Start	7.47	Rating **	M	Issue No.	935 (cont)	
LM End	7.47	Issue Type +	Ma	Location *	LS	
Category	Earthen Levee			GPS Latitude/Longitude		
				Start		End
Item	Encroachments			38.403795 °		38.403795 °
				-121.539205 °		-121.539205 °
DWR ID	DWR_RD0150_03_s_2012_935					
Comment Code						
PR : Prunings						
Inspector Comment						

Photo 2 of 2 : SP_2016_RD0150_17_935_20160219_00096.jpg



Prunings were found on the landside of the levee looking upstream. This picture was taken during fall 2011 inspection.

LM Start	7.70	Rating **	M	Issue No.	52
LM End	7.70	Issue Type +	Ma	Location *	WS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Encroachments			38.405536 °	38.405536 °
				-121.542752 °	-121.542752 °
DWR ID	DWR_RD0150_03_f_2015_52				
Comment Code					
TR : Tree or limb					
Inspector Comment					
Tree trunks and stumps might damage the levee toe during high water.					

Photo 1 of 1 : SP_2016_RD0150_17_52_20160219_00048.jpg



View of the tree trunk on the waterside toe of the levee.

* Location LS : Land Side N/A : Not Applicable WS : Water Side CR : Crown		** Rating A : Acceptable N : Not Inspected/Rated M : Minimally Acceptable C : Corrected U : Unacceptable A/W : Acceptable but Monitor & Maintain		+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	--	---	--	---

**Flood Control Project Maintenance
Levee Inspections**

Maintenance Issue Types Only, Levee Inspection Report By Mile - Spring 2016

Reclamation District No. 0150 Merrit Island

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 03 Elk Slough	Left	9.41	03/16/2016 03/16/2016	Pavel Kazi

LM Start	7.74	Rating **	M	Issue No.	396
LM End	7.74	Issue Type +	Ma	Location *	WS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Slope Stability			38.406098 °	38.406098 °
				-121.543028 °	-121.543028 °
DWR ID	DWR_RD0150_03_s_2015_396				
Comment Code					
S1 : Repair slope instability.					
Inspector Comment					
Slope instability caused by a tree.					

Photo 1 of 1 : SP_2016_RD0150_17_396_20160219_00092.jpg



Slope instability was found on the waterside toe of the levee looking upstream.

LM Start	8.02	Rating **	M	Issue No.	92
LM End	8.02	Issue Type +	Ma	Location *	WS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Slope Stability			38.409130 °	38.409130 °
				-121.539971 °	-121.539971 °
DWR ID	DWR_RD0150_03_s_2014_92				
Comment Code					
S1 : Repair slope instability.					
Inspector Comment					

Photo 1 of 2 : SP_2016_RD0150_17_92_20160219_00084.jpg



Updated picture of the slope instability on the waterside of the levee looking upstream during spring 2015 inspection.

* Location LS : Land Side N/A : Not Applicable WS : Water Side CR : Crown		** Rating A : Acceptable N : Not Inspected/Rated M : Minimally Acceptable C : Corrected U : Unacceptable A/W : Acceptable but Monitor & Maintain		+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	--	---	--	---

**Flood Control Project Maintenance
Levee Inspections**

Maintenance Issue Types Only, Levee Inspection Report By Mile - Spring 2016

Reclamation District No. 0150 Merrit Island

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 03 Elk Slough	Left	9.41	03/16/2016 03/16/2016	Pavel Kazi

LM Start	8.02	Rating **	M	Issue No.	92 (cont)	
LM End	8.02	Issue Type +	Ma	Location *	WS	
Category	Earthen Levee			GPS Latitude/Longitude		
				Start		End
Item	Slope Stability			38.409130 °		38.409130 °
				-121.539971 °		-121.539971 °
DWR ID	DWR_RD0150_03_s_2014_92					
Comment Code						
S1 : Repair slope instability.						
Inspector Comment						

Photo 2 of 2 : SP_2016_RD0150_17_92_20160219_00085.jpg



A slope instability was found on the waterside of the levee looking downstream.

LM Start	8.26	Rating **	M	Issue No.	65
LM End	8.26	Issue Type +	Ma	Location *	WS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Erosion / Bank Caving			38.408213 °	38.408213 °
				-121.535911 °	-121.535911 °
DWR ID	DWR_RD0150_03_f_2015_65				
Comment Code					
E1 : Note and monitor erosion site.					
Inspector Comment					

Photo 1 of 1 : SP_2016_RD0150_17_65_20160219_00063.jpg



View of erosion on the waterside of the levee.

LM Start	8.31	Rating **	M	Issue No.	66
LM End	8.31	Issue Type +	Ma	Location *	WS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Erosion / Bank Caving			38.407960 °	38.407960 °
				-121.534898 °	-121.534898 °
DWR ID	DWR_RD0150_03_s_2012_66				
Comment Code					
E1 : Note and monitor erosion site.					
Inspector Comment					

Photo 1 of 1 : SP_2016_RD0150_17_66_20160219_00064.jpg



Updated picture of the erosion on the waterside of the levee.

* Location
LS : Land Side N/A : Not Applicable
WS : Water Side
CR : Crown

** Rating
A : Acceptable N : Not Inspected/Rated
M : Minimally Acceptable C : Corrected
U : Unacceptable A/W : Acceptable but Monitor & Maintain

+ Issue Type
Ma : Maintenance Deficiency
Ob : Design & System Obsolescence
En : Enforcement

**Flood Control Project Maintenance
Levee Inspections**

Maintenance Issue Types Only, Levee Inspection Report By Mile - Spring 2016

Reclamation District No. 0150 Merrit Island

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 03 Elk Slough	Left	9.41	03/16/2016 03/16/2016	Pavel Kazi

LM Start	8.33	Rating **	U	Issue No.	67
LM End	8.33	Issue Type +	Ma	Location *	WS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Erosion / Bank Caving			38.407958 °	38.407958 °
				-121.534583 °	-121.534583 °
DWR ID	DWR_RD0150_03_s_2012_67				
Comment Code					
E1 : Note and monitor erosion site.					
Inspector Comment					

LM Start	8.33	Rating **	U	Issue No.	67 (cont)
LM End	8.33	Issue Type +	Ma	Location *	WS

Photo 1 of 2 : SP_2016_RD0150_17_67_20160219_00065.jpg



Updated picture of the erosion on the waterside shoulder looking upstream during spring 2014 inspection.

Photo 2 of 2 : SP_2016_RD0150_17_67_20160219_00066.jpg



Erosion was found on the waterside shoulder of the levee looking upstream. This picture was taken during fall 2012 inspection.

* Location LS : Land Side N/A : Not Applicable WS : Water Side CR : Crown		** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain		+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	--	---	--	---

**Flood Control Project Maintenance
Levee Inspections**

Maintenance Issue Types Only, Levee Inspection Report By Mile - Spring 2016

Reclamation District No. 0150 Merrit Island

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 03 Elk Slough	Left	9.41	03/16/2016 03/16/2016	Pavel Kazi

LM Start	8.37	Rating **	U	Issue No.	89
LM End	8.37	Issue Type +	Ma	Location *	WS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Animal Control			38.408153 °	38.408153 °
				-121.533980 °	-121.533980 °
DWR ID	DWR_RD0150_03_s_2012_89				
Comment Code					
A1 : Exterminate rodents and backfill and compact or grout burrows.					
Inspector Comment					

Photo 1 of 2 : SP_2016_RD0150_17_89_20160219_00081.jpg



Updated picture of a rodent hole on the waterside shoulder of the levee during spring 2015 inspection.

LM Start	8.37	Rating **	U	Issue No.	89 (cont)
LM End	8.37	Issue Type +	Ma	Location *	WS

Photo 2 of 2 : SP_2016_RD0150_17_89_20160219_00082.jpg



Updated picture of a rodent hole on the waterside shoulder of the levee during fall 2014 inspection.

LM Start	8.46	Rating **	N	Issue No.	90
LM End	8.46	Issue Type +	Ma	Location *	LS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Trim / Thin Trees			38.409220 °	38.409220 °
				-121.532801 °	-121.532801 °
DWR ID	DWR_RD0150_03_s_2012_90				
Comment Code					
T5 : Tree stumps.					
Inspector Comment					

Photo 1 of 1 : SP_2016_RD0150_17_90_20160219_00083.jpg



A tree stump was found on the landside of the levee looking upstream.

* Location		** Rating		+ Issue Type	
LS : Land Side	N/A : Not Applicable	A : Acceptable	N : Not Inspected/Rated	Ma : Maintenance Deficiency	
WS : Water Side		M : Minimally Acceptable	C : Corrected	Ob : Design & System Obsolescence	
CR : Crown		U : Unacceptable	A/W : Acceptable but Monitor & Maintain	En : Enforcement	

**Flood Control Project Maintenance
Levee Inspections**

Maintenance Issue Types Only, Levee Inspection Report By Mile - Spring 2016

Reclamation District No. 0150 Merrit Island

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 03 Elk Slough	Left	9.41	03/16/2016 03/16/2016	Pavel Kazi

LM Start	8.50	Rating **	N	Issue No.	55
LM End	8.50	Issue Type +	Ma	Location *	WS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Trim / Thin Trees			38.409559 °	38.409559 °
				-121.532356 °	-121.532356 °
DWR ID	DWR_RD0150_03_s_2012_55				
Comment Code					
T5 : Tree stumps.					
Inspector Comment					

Photo 1 of 1 : SP_2016_RD0150_17_55_20160219_00051.jpg



A tree stump was found on the waterside of the levee looking upstream.

LM Start	8.72	Rating **	M	Issue No.	7
LM End	8.72	Issue Type +	Ma	Location *	WS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Encroachments			38.411593 °	38.411593 °
				-121.529143 °	-121.529143 °
DWR ID	DWR_RD0150_03_s_2012_7				
Comment Code					
DE : Debris					
Inspector Comment					

Photo 1 of 1 : SP_2016_RD0150_17_7_20160219_00006.jpg



Broken concrete pipe was left on the waterside slope of the levee. The picture was taken from the crown looking upstream.

* Location LS : Land Side N/A : Not Applicable WS : Water Side CR : Crown		** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain		+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	--	---	--	---

**Flood Control Project Maintenance
Levee Inspections**

Maintenance Issue Types Only, Levee Inspection Report By Mile - Spring 2016

Reclamation District No. 0150 Merrit Island

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 03 Elk Slough	Left	9.41	03/16/2016 03/16/2016	Pavel Kazi

LM Start	9.21	Rating **	N	Issue No.	59
LM End	9.21	Issue Type +	Ma	Location *	WS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Trim / Thin Trees			38.413268 °	38.413268 °
				-121.525929 °	-121.525929 °
DWR ID	DWR_RD0150_03_s_2012_59				
Comment Code					
T5 : Tree stumps.					
Inspector Comment					

Photo 1 of 1 : SP_2016_RD0150_17_59_20160219_00055.jpg



A tree stump was found on the waterside of the levee looking upstream.

LM Start	9.35	Rating **	U	Issue No.	73
LM End	9.35	Issue Type +	Ma	Location *	WS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Trim / Thin Trees			38.413169 °	38.413169 °
				-121.523707 °	-121.523707 °
DWR ID	DWR_RD0150_03_s_2012_73				
Comment Code					
T3 : Trim and thin trees to allow visibility of the ground and room to flood fight.					
Inspector Comment					

Photo 1 of 1 : SP_2016_RD0150_17_73_20160219_00068.jpg



Thin/trim trees to allow for visibility of top 20' of waterward slope.

* Location
LS : Land Side N/A : Not Applicable
WS : Water Side
CR : Crown

** Rating
A : Acceptable
M : Minimally Acceptable
U : Unacceptable
N : Not Inspected/Rated
C : Corrected
A/W : Acceptable but Monitor & Maintain

+ Issue Type
Ma : Maintenance Deficiency
Ob : Design & System Obsolescence
En : Enforcement